



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

3

Inspection Report Minerals Regulatory Program January 31, 2013

Reviewed: 

Mine Name: Red Summit Mine	Permit Number: S/043/0031
Operator Name: PABCO Building Products, LLC	Inspection Date: November 03, 2010
Inspector(s): L Heppler	Time: 12:00 PM
Other Participants: Company Representative	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Bond Renewal Date: 03-30-2010 **Bond Amount:** \$20,700 **Permit fee** is up to date

Purpose of Inspection: Routine annual inspection. This site was inspected as a small mine site on 12/04/2008 by Brett Gregory

Inspection Summary: Toured the mine and surrounding area. There is a large high wall that is oversteepened and up to the property line, making future reclamation difficult. Much of the disturbance is historic; google earth photos go back to 1993, but UGS has older airphotos on file.

Photos were taken to document site conditions.

Conclusions and Recommendations: Bond amount is past due for escalation. Operator has the option of updating map and reducing disturbed acres. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 

LAH:vs

cc: PABCO Building Products LLC - John Hewitt

O:\M043-Summit\S0430031-RedSummit\inspections\Insp-11032010.doc






Overview from access road



Lower disturbed level



Waste dump on left of photo



Over steepened highwall